

HOME INSPECTION REPORT



42 Larkin Ave
Toronto

Prepared for: **Babiak Team**

Prepared by: **Bob Papadopoulos P.Eng., RHI** *

Inspection Date: **Aug 6 2024**



[www.redbrickinspections.ca](http://redbrickinspections.ca)
bob@redbrickinspections.ca
416-829-6655

Please Read: http://redbrickinspections.ca/docs/1_Introduction_Reference_Guide.pdf

Please Read: <https://redbrickinspections.ca/home-inspection-terms-and-conditions/>

Please Read: <http://redbrickinspections.ca/wp-content/uploads/2015/06/StandardsofPractice-OAHI-Rev.pdf>

* please see credentials at end of report

SIGNIFICANT ITEMS

*This page should not be considered as the complete report.
Please read all other forms contained within the Home
Inspection Report*

*For the purposes of this report,
the front of the house is considered
to be facing: South*

ROOFING The roof surfaces through-out are overall in good repair.

EXTERIOR Overall well maintained. See details for general repairs and maintenance.

STRUCTURE Overall well built house.

ELECTRICAL The 100 AMP service size is adequate though upgrading to 200 AMP likely if renovating. In addition to upgraded wiring there is knob and tube wiring-please see details.

HEATING 4-yr-old high-efficiency forced-air gas furnace with a typical life expectancy of 20-yrs.

COOLING/
HEAT PUMPS The air-conditioner is older. Continue servicing until replacement becomes necessary.

INSULATION/
VENTILATION Recommend additional insulation in the roof space to improve comfort and efficiency.

PLUMBING Overall good water pressure with copper supply piping. Further evaluation to main waste drain. The washrooms and kitchen are older though overall in good repair.

INTERIOR Overall well maintained. Older windows.

OVERALL RATING

The following rating reflects both the original quality of construction and the *overall* current condition of the home, based on a comparison to *similar* homes.



Below Typical

Typical

Above Typical

Prior to reviewing the Home Inspection Report please read the Terms and Conditions of the Home Inspection and the Standards of Practice of the Ontario Association of Home and Property Inspectors available online at:

www.redbrickinspections.ca

Description				
Roofing Material:	Location:	Leakage Probability:	Chimney(s) Type:	Location:
Asphalt Shingles:	Slope:	Low	Brick:	East
Asphalt Shingles:	Garage:	Low		
Metal:	Bay:	Low	west	
Asphalt Shingles:	Bay(s):	Low	south	

Limitations		
Roof Inspected By:	Access Limited By:	Chimney Access Limited By:
From Grade	Height Tree	

Observations/Recommendations

Tree Branches: [retain arbourist for annual monitoring/trimming](#)

Sloped Surface: [overall surface in good repair](#)

Chimney(s): [rebuilt and in good repair](#)



Garage: [overall surface in good repair](#)



Bay(s): [overall surface in good repair](#)

[west: paint metal surface](#)

Description

Gutters & Downspouts: Aluminum:	Downspout(s) Discharge: Below/Above Grade	Lot Topography: Flat	Walls & Wall Structures: Brick Metal Siding Wood siding
------------------------------------	--	-------------------------	--

Limitations

Exterior Inspection from Ground Level
Storage Against Wall

Flora Against Building Restricted Inspection

Observations/Recommendations


- **Gutters/Downspouts: requires maintenance/cleaning
extend 6-ft away from house
- **Walk(s)/Driveway(s): overall in good repair
- WALL SURFACES:
 - Brick: overall in good repair
 - Wood siding: overall in good repair
- DOORS/WINDOWS: older, overall in good repair



PORCH rusting railings, see Structure Concrete floors

DETACHED GARAGE: older, typically ongoing repairs
bottom perimeter prone to rot - repair as required, budget to repair perimeter

**BASEMENT WALKOUT: overall well built, service drain at bottom landing, replace door
improve railings for safety



Note: Maintain Gutters & Downspouts annually. Extend Downspouts at least 6-feet away from the house

** Any or all these items may contribute to **Basement Leakage**. Please see Interior Page

Description

Configuration: Basement:	Foundations: Stone Brick	Floor : Wood Joists	Walls : Masonry (Double-Brick) Wood Frame (Siding)	Roof/Ceiling Framing: Wood Rafters/Joists
-----------------------------	--------------------------------	------------------------	--	--

Limitations

Restricted Access to: Wall Space	Foundation Wall Not Visible: _____ % Roof Space Inspected From Access Hatch
-------------------------------------	--

Observations/Recommendations

overall well built house

FOUNDATIONS: general mortar repairs as required



ROOF: overall in good repair



FLOORS:

Concrete Floors: front porch, underside spalling- repair and seal top side surface
exterior corner damage- repair



Description


Service Size: 100 AMP (240volts)	Service Entrance Cable: Location: Overhead	Distribution Wire: Copper
Main Disconnect/Service Box Rating: 100 AMP	Type of material: Not Visible	Grounded & Ungrounded
Description: Breakers		Knob-and-Tube-Copper
Location: Basement		Non-metallic Sheathed
Distribution Panel Rating: 100 AMP	System Grounding: Description: Copper	Metallic Sheathed
Description: Breakers	Location: Water Pipe	Ground Fault Circuit Interrupter: Location:
Location: Basement		Bathroom(s)
Auxiliary Panel(s): Rating: 75 AMP	Outlets Description: Grounded/Ungrounded	
Description: Breakers	Number of Outlets: Minimal	Arc Fault Circuit Interrupter: Location:
Location: Basement		

Limitations


Main Disconnect Cover Not Removed

Observations/Recommendations

SERVICE ENTRANCE: **anticipate upgrade if renovating**
 Service Size: **anticipate upgrade if renovating to 200 amp when renovating**
 SERVICE PANEL: **crowded though overall in good repair**
anticipate upgrade if renovating to 200 amp when renovating
 Grounding: **replace clamp at water main**



BRANCH WIRING: **based on random sampling observed over 50% likely require upgrading for insurance purposes**
for insurance option contact David Slack 1-800-971-1363 of David Slack
 Comments: **power wires from house to garage - older, anticipate replacement**



Note 1: All recommendations are safety issues - Treat them as high priority.

Note 2: Please ensure accurate labelling on panels.

REFERENCE LINK http://redbrickinspections.ca/docs/6_Heating_Reference_Guide.pdf

42 Larkin Ave

HEATING

Aug 6 2024

page 6

Description

Description:	Efficiency:	Rated Input:	Approx. Age:	Life Expectancy:	Fuel Type:	Shut Off at:
Forced Air Furnace:	High	80 x1000BTU/hr	4 yrs.	20 yrs.	Gas	Meter-Exterior

Exhaust Vent Arrangement: [Plastic Through-Wall Vent](#)

Limitations

[Heat Loss Calculations Not Done](#)
[Heat Exchanger- Inaccessible](#)

[A/C Presently Operating](#)

Furnace Performance

Supply Temp F:
Return Temp F:

Observations/Recommendations

FORCED AIR FURNACE: [service annually](#)



Radiator(s): [abandoned when system was replaced with forced air duct system](#)

REFERENCE LINK

http://redbrickinspections.ca/docs/7_AC_Heat_Pump_Reference_Guide.pdf

42 Larkin Ave

COOLING/Heat Pumps

Aug 6 2024

page 7

Description

Description:	Cooling Capacity:	Approx. Age:	Typical Life Expectancy:
Air Conditioner (air-cooled):	36 x1,000 BTU/hr	23 yrs. old	15 to 20 yrs.

Limitations

Cooling Performance

Supply Temp F:	55
Return Temp F:	70

Observations/Recommendations

AIR CONDITIONER: **old unit, continue servicing until replacement becomes necessary**



REFERENCE LINK

http://redbrickinspections.ca/docs/8_Insulation_Ventilation_Reference_Guide.pdf

42 Larkin Ave

INSULATION/VENTILATION

Aug 6 2024

page 8

Description

Material:	Location	R-Value	Air/Vapour Barrier:	Venting:
Fiberglass:	Main Roof:	24	None Found	Roof

Limitations

Roof Space Inspected from Access Hatch

Access Not Gained To Wall Space

Observations/Recommendations

ROOF SPACE: recommend upgrading insulation to improve comfort and efficiency
recommend improving ventilation with soffit vents
insulate and weather-strip access hatch to roof space



Note: adding insulation is considered an improvement rather than a repair

R-values are estimated

Description

Service Piping into House: Not determined	Main Shut Off Valve at: Basement-Front	Water Flow (Pressure): Good
Supply Piping & Pump(s): Copper	Waste Piping & Pump(s): Plastic Cast Iron	Water Heater Type: Conventional Fuel Type: Electricity Capacity: 40 Gal Age Yrs.: 15 Life Expectancy: 20

Limitations

Isolating/Relief Valves & Main Shut Off Valves Not Tested	Concealed Plumbing not Inspected
Kitchen and Laundry Appliances Were Not Inspected	Tub/Sink Overflows Not Tested

Observations/Recommendations

WATERMAIN: not determined - appears to be older, further evaluation, contact city to arrange replacement
lead testing kits available from city centers

SUPPLY PIPING: all piping examined was in good repair

WASTE PIPING: all piping examined was in good repair

Basement Floor Drain: basement floor drain not found, further evaluation required
likely under subfloor
suspect older main drain, recommend video-scan, risk of tree roots
may require repairs/replacement
recommend installing backflow valve to main waste drain

Washroom(s): older though overall in good repair
anticipate renovations

Kitchen(s) older though overall in good repair
anticipate renovations

Description

Floor Finishes: Wood Resilient Ceramic Tile	Wall Finishes: Plaster/Drywall	Ceiling Finishes: Plaster/Drywall	Windows: Single/Double Hung Casement Primary Plus Storm Double Glazing	Exterior Doors: Wood
Fireplaces: Masonry	Fireplace Fuel: Wood			

Limitations

Restricted/No Access To: _____ Foundation Not Visible 0 %
 CO Detectors, Security Systems, Central Vacuum, Chimney Flues Not Inspected Drainage Tile Not Visible
 Storage/Furnishings in Some Areas Limited Inspection

Observations/Recommendations

Floors: cold room: older tile suspect to contain asbestos
 encapsulating is often the best approach
 Environmental Consultants can assist if this is a concern

Floors/Walls/Ceilings: overall in good repair

Trim/Cabinets/Counters: overall in good repair

Windows/Doors: older units, upgrade as required or if renovating

FIREPLACE: recommend chimney sweep/inspection by W.E.T.T. Certified technician
 (www.wettinc.ca)

**Basement Leakage: presently no leaking detected with moisture meter random sampling
 typical efflorescence, staining and dampness for older foundation
 see steps below
 consider damp-proofing if renovating basement

CO/Smoke detectors: please ensure one per level each with annual maintenance, this is a life safety concern and mandatory by law

** Steps recommended in order to minimize basement leakage

- gutters, downspouts, grading, driveways: ongoing maintenance and repair/see Exterior
- cracks/form ties on foundation: monitor/repair as required
- excavation/damp-proofing: monitor basement, consider step 3 as a last resort

Environmental/Health Concerns: http://redbrickinspections.ca/docs/11_Environmental_Reference_Guide.pdf



Bob Papadopoulos P.Eng, RHI

- **Over 20 years of building inspecting experience in Toronto and the GTA**
- **Over 6,000 residential and commercial buildings inspected**

Bob has inspected over 6,000 residential and commercial buildings of various descriptions and reporting on conditions of major systems including structure, building envelope and mechanical systems, specific problem investigations and pre-renovation inspections. In the past Bob has helped train Home Inspectors and assisted in the creation of educational courses on home inspecting as well as taught Home Inspection courses at Seneca College. Bob also has experience in the construction industry inspecting many large scale projects through-out the GTA. He also served in the Canadian Navy as a Marine Mechanic and Ships Team Diver.

Professional Designations

- P.Eng. (Professional Engineer of Ontario) <http://www.peo.on.ca/>
 - RHI Registered Home Inspector <http://www.oahi.com/>
 - Environmental Site Assessment: ESA Phase 1 Certified <http://aesac.ca/>
-