

HOME INSPECTION REPORT



131 Colbeck St
Toronto

Prepared for: [Kristofer Lawson](#)

Prepared by: Bob Papadopoulos P.Eng., RHI *

Inspection Date: [Feb 28 2025](#)



www.redbrickinspections.ca
bob@redbrickinspections.ca
416-829-6655

Please Read: http://redbrickinspections.ca/docs/1_Introduction_Reference_Guide.pdf

Please Read: <https://redbrickinspections.ca/home-inspection-terms-and-conditions/>

Please Read: <http://redbrickinspections.ca/wp-content/uploads/2015/06/StandardsofPractice-OAHI-Rev.pdf>

* please see credentials at end of report

SIGNIFICANT ITEMS

*This page should not be considered as the complete report.
Please read all other forms contained within the Home
Inspection Report*

*For the purposes of this report,
the front of the house is considered
to be facing: North*

ROOFING The roof surfaces where visible are overall in good repair.

EXTERIOR Overall well maintained.

STRUCTURE Overall well built house.

ELECTRICAL The 200 AMP service size is adequate and the wiring has been upgraded to copper grounded.

HEATING 1-yr-old high-efficiency gas-fired hot-water boiler (combination provides house heating and domestic hot water) with a typical life expectancy of 15 to 20-yrs.

COOLING/
HEAT PUMPS The ductless air-conditioner is older. Continue servicing until replacement becomes necessary.

INSULATION/
VENTILATION The house was recently renovated and reported spray foam installed in roof, main floor and basement walls which is above average.

PLUMBING Overall good water pressure with copper and plastic supply piping. A backflow valve has been installed to the main waste drain. The washrooms and kitchen have recently been renovated and in good repair.

INTERIOR Recently renovated.

OVERALL RATING

The following rating reflects both the original quality of construction and the *overall* current condition of the home, based on a comparison to *similar* homes.

Below Typical

Typical

Above Typical

Prior to reviewing the Home Inspection Report please read the Terms and Conditions of the Home Inspection and the Standards of Practice of the Ontario Association of Home and Property Inspectors available online at:

www.redbrickinspections.ca

Description				
Roofing Material: Asphalt Shingles:	Location: Slope:	Leakage Probability: Low	Chimney(s) Type: Brick: Brick Abandoned:	Location: East West

Limitations		
Roof Inspected By: From Grade	Access Limited By: Height Snow	Chimney Access Limited By: Height

Observations/Recommendations

Tree Branches: [retain arbourist for annual monitoring/trimming](#)

Sloped Surface: [where visible overall surface in good repair](#)

Chimney: [overall in good repair](#)



Porch(s): [mostly not visible due to snow](#)
[overall surface in good repair](#)



[Note: Recommend Annual Maintenance Contract for Roof Surface, Flashing Details and Chimney\(s\)](#)

Description

Gutters & Downspouts: Aluminum: Galvanized Steel:	Downspout(s) Discharge: Various Above Grade	Lot Topography: Flat	Walls & Wall Structures: Brick
---------------------------------------------------------	------------------------------------------------	-------------------------	-----------------------------------

Limitations

Exterior Inspection from Ground Level
 Snow over Decks/Porches

Observations/Recommendations

- **Gutters/Downspouts: [requires maintenance/cleaning](#)
- ** Downspouts: [extend 6-ft away from house](#)
- **Landscaping: [retain arbourist for annual monitoring/trimming](#)

WALL SURFACES: [overall in good repair](#)
 DOORS/WINDOWS: [overall in good repair](#)



PORCH [overall in good repair](#)
 DECK [overall in good repair](#)

Note: Maintain Gutters & Downspouts annually. Extend Downspouts at least 6-feet away from the house

** Any or all these items may contribute to **Basement Leakage**. Please see Interior Page

REFERENCE LINK

http://redbrickinspections.ca/docs/4_Structure_Reference_Guide.pdf

131 Colbeck St

STRUCTURE

Feb 28 2025

page 4

Description

Configuration: Basement:	Foundations: Brick	Floor : Wood Joists	Walls : Masonry (Double-Brick)	Roof/Ceiling Framing: Not Visible
-----------------------------	-----------------------	------------------------	-----------------------------------	--------------------------------------

Limitations

Restricted Access to: Wall Space Roof Space	Foundation Wall Not Visible: <u>95</u> %
---------------------------------------------------	------------------------------------------

Observations/Recommendations

overall well built house

WALLS:

Masonry Arches: rear: typical settlement cracks
monitor-cracks above arch typical, repair mortar as required



Description

Service Size: 200 AMP (240volts)	Service Entrance Cable:	Distribution Wire:
Main Disconnect/Service Box	Location: Overhead	Copper
Rating: 200 AMP	Type of material: Not Visible	Grounded
Description: Breakers		
Location: Basement		
Distribution Panel	System Grounding:	
Rating: 200 AMP	Description: Copper	
Description: Breakers	Location: Water Pipe	Ground Fault Circuit Interrupter:
Location: Basement		Location: Outside Kitchen Bathroom(s)
Auxiliary Panel(s):	Outlets	
Rating: AMP	Description: Grounded	
Description:	Number of Outlets: Upgraded	Combo Arc Fault Circuit Interrupter:
Location:		Location: Panel

Limitations

Main Disconnect Cover Not Removed

Observations/Recommendations

SERVICE ENTRANCE: overall in good repair
 SERVICE PANEL: overall in good repair
 panel obstructed by cabinet - cover not removed



BRANCH WIRING: random sampling determined the wiring has been upgraded throughout

Note 1: All recommendations are safety issues - Treat them as high priority.

Note 2: Please ensure accurate labelling on panels.

REFERENCE LINK

http://redbrickinspections.ca/docs/6_Heating_Reference_Guide.pdf

131 Colbeck St

HEATING

Feb 28 2025

page 6

Description

Description:	Efficiency:	Rated Input:	Approx. Age:	Life Expectancy:	Fuel Type:	Shut Off at:
Hot Water Boiler:	High	150 x1000BTU/hr	1 yrs.	15 to 20 yrs.	Gas	Meter-Exterior
Combination System:						

Exhaust Vent Arrangement: [Plastic Through-Wall Vent](#)

Limitations

[Heat Loss Calculations Not Done](#)
[Heat Exchanger- Inaccessible](#)

Boiler Performance

Pressure lbs/in2: [16](#)
Temp Deg F: [140](#)

Observations/Recommendations

THERMOSTAT: [multi thermostats for zone control provides better comfort/efficiency](#)

HOT WATER BOILER: [service annually](#)

COMBINATION SYSTEM: [provides house heating \(radiators\) and domestic hot water](#)



Radiator(s): [some newer units](#)
[older units: monitor/repair valves as required](#)

Comments: [3rd level \(previously attic\) was renovated and portable heating installed, recommend installing fixed heating source, i.e. electric baseboard or extend hydronic system and install radiator, or install ductless heat pump for heating/cooling](#)

REFERENCE LINK

http://redbrickinspections.ca/docs/7_AC_Heat_Pump_Reference_Guide.pdf

131 Colbeck St

COOLING/Heat Pumps

Feb 28 2025

page 7

Description

Description:	Cooling Capacity:	Approx. Age:	Typical Life Expectancy:
Ductless (air-cooled)	18 x1,000 BTU/hr	est. 15 yrs. old	15 to 20 yrs.

Limitations

Cannot Test With Low Outdoor Temp

Cooling Performance

Supply Temp F:
Return Temp F:

Observations/Recommendations

DUCTLESS A/C: not tested: should be serviced before using
aging unit, continue servicing until replacement becomes necessary



Comments: 3rd level typically more difficult to cool- may require supplemental unit
i.e. ductless heat pump

Description

Material:	Location	R-Value	Air/Vapour Barrier:	Venting:
Spray foam:				Roof

Limitations

Access Not Gained To Wall Space
 Access Not Gained To Roof Space

Observations/Recommendations

house was recently renovated and reported spray foam installed in roof, main floor and basement walls which is above average, reported 2nd level walls were not part of renovation

Description

Service Piping into House: Copper	Main Shut Off Valve at: Basement-Front	Water Flow (Pressure): Good
Supply Piping & Pump(s): Copper Plastic	Waste Piping & Pump(s): Plastic Plastic Floor Drain	Water Heater see Heating Type: Combination Fuel Type: Capacity: Age Yrs.: Life Expectancy:

Limitations

Isolating/Relief Valves & Main Shut Off Valves Not Tested	Concealed Plumbing not Inspected
Kitchen and Laundry Appliances Were Not Inspected	Tub/Sink Overflows Not Tested

Observations/Recommendations

WATERMAIN: [upgraded to copper](#)

SUPPLY PIPING: [newly installed](#)
[all piping examined was in good repair](#)

WASTE PIPING: [newly installed](#)
[all piping examined was in good repair](#)
[a back flow valve has been installed to the main waste drain](#)

Washroom(s): [recently renovated](#)

Kitchen(s) [recently renovated](#)

Description

Floor Finishes:	Wall Finishes:	Ceiling Finishes:	Windows:	Exterior Doors:
Wood	Plaster/Drywall	Plaster/Drywall	Casement	Wood
Ceramic Tile			Fixed	French
Carpet			Double Glazing	
			Sliders	
Fireplaces:	Fireplace Fuel:			
Insert	Gas			

Limitations

Restricted/No Access To: _____ Foundation Not Visible 95 %
 CO Detectors, Security Systems, Central Vacuum, Chimney Flues Not Inspected Drainage Tile Not Visible
 Absence of Historical Clues due to New Finishes/Paint
 Storage/Furnishings in Some Areas Limited Inspection

Observations/Recommendations

Floors/Walls/Ceilings: [recently renovated](#)

Trim/Cabinets/Counters: [recently renovated](#)

Windows/Doors: [upgraded double glazed units](#)

FIREPLACE: [tested functional, service annually](#)

**Basement Leakage: [presently no leaking detected with moisture meter random sampling](#)

STAIRS: [provide hand rails to third level steps](#)

CO/Smoke detectors: [please ensure one per level each with annual maintenance, this is a life safety concern and mandatory by law](#)

** Steps recommended in order to minimize basement leakage

1. gutters, downspouts, grading, driveways: [ongoing maintenance and repair/see Exterior](#)
2. cracks/form ties on foundation: [monitor/repair as required](#)
3. excavation/damp-proofing: [monitor basement, consider step 3 as a last resort](#)

Environmental/Health Concerns: http://redbrickinspections.ca/docs/11_Environmental_Reference_Guide.pdf



Bob Papadopoulos P.Eng, RHI

- **Over 20 years of building inspecting experience in Toronto and the GTA**
- **Over 6,000 residential and commercial buildings inspected**

Bob has inspected over 6,000 residential and commercial buildings of various descriptions and reporting on conditions of major systems including structure, building envelope and mechanical systems, specific problem investigations and pre-renovation inspections. In the past Bob has helped train Home Inspectors and assisted in the creation of educational courses on home inspecting as well as taught Home Inspection courses at Seneca College. Bob also has experience in the construction industry inspecting many large scale projects through-out the GTA. He also served in the Canadian Navy as a Marine Mechanic and Ships Team Diver.

Professional Designations

- P.Eng. (Professional Engineer of Ontario) <http://www.peo.on.ca/>
 - RHI Registered Home Inspector <http://www.oahi.com/>
 - Environmental Site Assessment: ESA Phase 1 Certified <http://aesac.ca/>
-