

HOME INSPECTION REPORT



29 Richland Cres

Toronto

Prepared for: [The Babiak Team](#)

Prepared by: Bob Papadopoulos P.Eng., RHI *

Inspection Date: [March 17 2026](#)



www.redbrickinspections.ca
bob@redbrickinspections.ca
416-829-6655

Please Read: http://redbrickinspections.ca/docs/1_Introduction_Reference_Guide.pdf

Please Read: <https://redbrickinspections.ca/home-inspection-terms-and-conditions/>

Please Read: <http://redbrickinspections.ca/wp-content/uploads/2015/06/StandardsofPractice-OAHI-Rev.pdf>

* please see credentials at end of report

SIGNIFICANT ITEMS

*This page should not be considered as the complete report.
Please read all other forms contained within the Home
Inspection Report*

*For the purposes of this report,
the front of the house is considered
to be facing: North*

ROOFING The roof surfaces through-out are overall in good repair.

EXTERIOR Overall well maintained. See details for general repairs and maintenance.

STRUCTURE Overall well built house.

ELECTRICAL The 100 AMP service size is adequate and the wiring is copper grounded.

HEATING 4-yr-old high-efficiency forced-air gas furnace with a typical life expectancy of 20-yrs.

COOLING/
HEAT PUMPS 4-yr-old air-conditioner with a typical life expectancy of 15-yrs.

INSULATION/
VENTILATION Roof space insulation (upgraded) and ventilation is adequate

PLUMBING Overall good water pressure with copper supply piping. The washrooms and kitchen have been renovated and in good repair.

INTERIOR Overall well maintained.

OVERALL RATING

The following rating reflects both the original quality of construction and the *overall* current condition of the home, based on a comparison to *similar* homes.

Below Typical

Typical

Above Typical

Prior to reviewing the Home Inspection Report please read the Terms and Conditions of the Home Inspection and the Standards of Practice of the Ontario Association of Home and Property Inspectors available online at:

www.redbrickinspections.ca

REFERENCE LINK http://redbrickinspections.ca/docs/2_Roofing_Reference_Guide.pdf

29 Richland Cres

ROOFING/Chimneys

March 17 2026

page 2

Description

Roofing Material: Asphalt Shingles:	Location: Slope:	Leakage Probability: Low	Chimney(s) Type: Brick Shared:	Location: East
--	---------------------	-----------------------------	-----------------------------------	-------------------

Limitations

Roof Inspected By: From Grade	Access Limited By: Height Snow	Chimney Access Limited By: Height
----------------------------------	--------------------------------------	--------------------------------------

Observations/Recommendations

Roofing: overall surface in good repair where visible



Chimney(s): overall in good repair

Note: Recommend Annual Maintenance Contract for Roof Surface, Flashing Details and Chimney(s)

Description

Gutters & Downspouts: Aluminum:	Downspout(s) Discharge: Various Above Grade	Lot Topography: Flat	Walls & Wall Structures: Brick
------------------------------------	--	-------------------------	-----------------------------------

Limitations

Exterior Inspection from Ground Level


Observations/Recommendations

WALL SURFACES: overall in good repair
DOORS/WINDOWS: overall in good repair



PORCH

Column(s) monitor/budget to repair/replace
Step(s): settlement: monitor/repair



**Grading: re-grade pavers away from house

**Driveway(s): budget to resurface, gas line: contact utility to install collision post for gas line



Note: Maintain Gutters & Downspouts annually. Extend Downspouts at least 6-feet away from the house

** Any or all these items may contribute to **Basement Leakage**. Please see Interior Page

Description

Configuration:	Foundations:	Floor :	Walls :	Roof/Ceiling Framing:
Basement:	Masonry Block	Wood Joists	Masonry (Double-Brick)	Wood Rafters/Joists
Crawl Space:	Masonry Block			

Limitations

Restricted Access to: Wall Space	Foundation Wall Not Visible: <u>95</u> % Roof Space Inspected From Access Hatch
-------------------------------------	--


Observations/Recommendations

overall well built house

FOUNDATIONS: typical settlement cracks/mortar repairs - continue to monitor, repair parging

WALLS:

Masonry: typical settlement cracks/mortar repairs - continue to monitor



ROOF: overall in good repair

Comments: main level: ceiling was modified to open concept and roof/ceiling structure was reinforced, overall performance appears adequate



Description

Service Size: 100 AMP (240volts)	Service Entrance Cable:	Distribution Wire:
Main Disconnect/Service Box	Location: Overhead	Copper
Rating: 100 AMP	Type of material: Not Visible	Grounded
Description: Breakers		
Location: Basement		
Distribution Panel	System Grounding:	
Rating: 100 AMP	Description: Copper	
Description: Breakers	Location: Water Pipe	Ground Fault Circuit Interrupter:
Location:		Location: Outside Kitchen
Auxiliary Panel(s):	Outlets	Bathroom(s)
Rating: AMP	Description: Grounded	
Description:	Number of Outlets:	Arc Fault Circuit Interrupter:
Location:		Location:

Limitations


Main Disconnect Cover Not Removed

Observations/Recommendations

SERVICE ENTRANCE:

Mast: **rusting, maintenance as required**

SERVICE PANEL: **overall in good repair**



Note 1: All recommendations are safety issues - Treat them as high priority.

Note 2: Please ensure accurate labelling on panels.

Description

Description: Efficiency: Rated Input: Approx. Age: Life Expectancy: Fuel Type: Shut Off at:
 Forced Air Furnace: High 66 x1000BTU/hr 4 yrs. 20 yrs. Gas Meter-Exterior

Exhaust Vent Arrangement: Plastic Through-Wall Vent

Limitations

Furnace Performance

Heat Loss Calculations Not Done
 Heat Exchanger- Inaccessible

Supply Temp F: 110
 Return Temp F: 70

Observations/Recommendations

FORCED AIR FURNACE: service annually
 Filter: replace 1-per-6 to 12 months



Registers: insulation around registers may contain asbestos
 encapsulating the insulation is often the best approach
 Environmental Consultants can assist if this is a concern



REFERENCE LINK

http://redbrickinspections.ca/docs/7_AC_Heat_Pump_Reference_Guide.pdf

29 Richland Cres

COOLING/Heat Pumps

March 17 2026

page 7

Description

Description:	Cooling Capacity:	Approx. Age:	Typical Life Expectancy:
Air Conditioner (air-cooled):	24 x1,000 BTU/hr	4 yrs. old	10 to 15 yrs.

Limitations

Cannot Test With Low Outdoor Temp

Cooling Performance

Supply Temp F:
Return Temp F:

Observations/Recommendations

AIR CONDITIONER: not tested: should be serviced before using



Description

Material:	Location	R-Value	Air/Vapour Barrier:	Venting:
Fiberglass/Cellulose:	Main Roof:	40	Not Visible	Roof
Fiberglass/Cellulose:	2nd Roof:	?		

Limitations

Observations/Recommendations

ROOF SPACE:
 Main Slope Roof: [lower roof:](#)
[insulation has been upgraded which will improve comfort and efficiency](#)



2nd Slope Roof: [limited access: insulation not determined](#)



Description

Service Piping into House: Copper	Main Shut Off Valve at: Basement	Water Flow (Pressure): Good
Supply Piping & Pump(s): Copper Plastic	Waste Piping & Pump(s): Plastic Copper	Water Heater Type: Induced Draft Fuel Type: Gas Capacity: 40 Gal Age Yrs.: 7 Life Expectancy: 15

Limitations

Isolating/Relief Valves & Main Shut Off Valves Not Tested	Concealed Plumbing not Inspected
Kitchen and Laundry Appliances Were Not Inspected	Tub/Sink Overflows Not Tested

Observations/Recommendations

SUPPLY PIPING: all piping examined was in good repair

WASTE PIPING: all piping examined was in good repair

Basement Floor Drain: not found: main drain to city sewer- recommend video-scan
recommend installing backflow valve to main waste drain

Washroom(s): renovated, overall in good repair

Kitchen(s) renovated, overall in good repair

Description				
Floor Finishes:	Wall Finishes:	Ceiling Finishes:	Windows:	Exterior Doors:
Wood	Plaster/Drywall	Plaster/Drywall	Casement	Metal
Ceramic Tile	Paneling	Paneling	Sliders	Storm
Carpet			Fixed	
			Double Glazing	
Fireplaces:	Fireplace Fuel:			

Limitations	
Restricted/No Access To: _____	Foundation Not Visible <u>95</u> %
CO Detectors, Security Systems, Central Vacuum, Chimney Flues Not Inspected	Drainage Tile Not Visible
Absence of Historical Clues due to New Finishes/Paint	

Observations/Recommendations

Floors/Walls/Ceilings: [overall in good repair](#)

Trim/Cabinets/Counters: [overall in good repair](#)

Windows/Doors: [overall in good repair](#)

STAIRS: [provide hand rails to lower basement steps](#)

**Basement Leakage: [presently no leaking detected with moisture meter random sampling](#)

**Crawlspace Leakage: [typical efflorescence, staining and dampness for older foundation see steps below](#)

CO/Smoke detectors: [please ensure one per level each with annual maintenance, this is a life safety concern and mandatory by law](#)

** Steps recommended in order to minimize basement leakage

- gutters, downspouts, grading, driveways: [ongoing maintenance and repair/see Exterior](#)
- cracks/form ties on foundation: [monitor/repair as required](#)
- excavation/damp-proofing: [monitor basement, consider step 3 as a last resort](#)

Environmental/Health Concerns: http://redbrickinspections.ca/docs/11_Environmental_Reference_Guide.pdf



Bob Papadopoulos P.Eng, RHI

- **Over 20 years of building inspecting experience in Toronto and the GTA**
- **Over 6,000 residential and commercial buildings inspected**

Bob has inspected over 6,000 residential and commercial buildings of various descriptions and reporting on conditions of major systems including structure, building envelope and mechanical systems, specific problem investigations and pre-renovation inspections. In the past Bob has helped train Home Inspectors and assisted in the creation of educational courses on home inspecting as well as taught Home Inspection courses at Seneca College. Bob also has experience in the construction industry inspecting many large scale projects through-out the GTA. He also served in the Canadian Navy as a Marine Mechanic and Ships Team Diver.

Professional Designations

- P.Eng. (Professional Engineer of Ontario) <http://www.peo.on.ca/>
 - RHI Registered Home Inspector <http://www.oahi.com/>
 - Environmental Site Assessment: ESA Phase 1 Certified <http://aesac.ca/>
-