

HOME INSPECTION REPORT



45 Montye Ave & Lane House Toronto

Prepared for: [The Babiak Team](#)

Prepared by: Bob Papadopoulos P.Eng., RHI *

Inspection Date: [March 10 2026](#)



www.redbrickinspections.ca
bob@redbrickinspections.ca
416-829-6655

Please Read: http://redbrickinspections.ca/docs/1_Introduction_Reference_Guide.pdf

Please Read: <https://redbrickinspections.ca/home-inspection-terms-and-conditions/>

Please Read: <http://redbrickinspections.ca/wp-content/uploads/2015/06/StandardsofPractice-OAHI-Rev.pdf>

* please see credentials at end of report

SIGNIFICANT ITEMS

*This page should not be considered as the complete report.
Please read all other forms contained within the Home
Inspection Report*

*For the purposes of this report,
the front of the house is considered
to be facing: North*

ROOFING The roof surfaces through-out are overall in good repair. New Lane House.

EXTERIOR Overall well maintained.

STRUCTURE Overall well built house with newly built Lane House.

ELECTRICAL The 200 AMP service size is adequate and the wiring is copper grounded and ungrounded (some knob and tube)-see details. New wiring in Lane House.

HEATING The forced-air gas furnace is older. Continue servicing until replacement becomes necessary. Lane House: two new units.

COOLING/
HEAT PUMPS The air-conditioner is older. Continue servicing until replacement becomes necessary.

INSULATION/
VENTILATION Roof space insulation (upgraded and ventilation is adequate. The Lane House includes an HRV (heat recovery ventilator) to improve air quality and efficiency.

PLUMBING Overall good water pressure with copper (Lane House: plastic) supply piping. The washrooms and kitchen (new Lane House) are in good repair.

INTERIOR Overall well maintained. Newly built Lane House.

OVERALL RATING

The following rating reflects both the original quality of construction and the *overall* current condition of the home, based on a comparison to *similar* homes.

Below Typical

Typical

Above Typical

Prior to reviewing the Home Inspection Report please read the Terms and Conditions of the Home Inspection and the Standards of Practice of the Ontario Association of Home and Property Inspectors available online at:

www.redbrickinspections.ca

Description				
Roofing Material:	Location:	Leakage Probability:	Chimney(s) Type:	Location:
Asphalt Shingles:	Slope:	Low	Brick:	Central
Asphalt Shingles:	2nd Slope:	Low	Lane House	



Limitations		
Roof Inspected By:	Access Limited By:	Chimney Access Limited By:
From Grade	Height	Height

Observations/Recommendations

Sloped Surface: [overall surface in good repair](#)



2nd Slope: [Lane House, newly installed](#)



[Note: Recommend Annual Maintenance Contract for Roof Surface, Flashing Details and Chimney\(s\)](#)

Description

Gutters & Downspouts: Aluminum:	Downspout(s) Discharge: Below/Above Grade	Lot Topography: Flat	Walls & Wall Structures: Brick Insulbrick
------------------------------------	--	-------------------------	---

Limitations

Exterior Inspection from Ground Level

Observations/Recommendations

WALL SURFACES:

Brick: overall in good repair

Artificial Stone: may require covering with metal siding for insurance
repair seams as required, budget to cover/replace with metal siding

DOORS/WINDOWS: overall in good repair



PORCH front steps settlement - repair



Windows: low to grade - prone to leaking



Note: Maintain Gutters & Downspouts annually. Extend Downspouts at least 6-feet away from the house

** Any or all these items may contribute to **Basement Leakage**. Please see Interior Page

REFERENCE LINK

http://redbrickinspections.ca/docs/4_Structure_Reference_Guide.pdf

45 Montye Ave & Lane House

STRUCTURE

March 10 2026

page 4

Description

Configuration:	Foundations:	Floor :	Walls :	Roof/Ceiling Framing:
Basement:	Stone	Wood Joists	Masonry (Double-Brick)	Wood Rafters/Joists
Crawl Space:	Piers		Wood Frame (Siding)	

Limitations

Restricted Access to:	Foundation Wall Not Visible: <u>60</u> %
Wall Space	Roof Space Inspected From Access Hatch
Crawl Space	

Observations/Recommendations


overall well built house

FOOTINGS/FOUNDATIONS basement floor has been lowered
basement: support column added to support main level floor

WALLS:
Masonry: mortar repairs as required

FOUNDATIONS: general parging maintenance as required

ROOF: overall in good repair



overall well built new Lane House



Description



Service Size: 200 AMP (240volts)	Service Entrance Cable:	Distribution Wire:
Main Disconnect/Service Box	Location: Overhead	Copper
Rating: 100 AMP	Type of material: Not Visible	Grounded & Ungrounded
Description: Fuses Breakers		Knob-and-Tube-Copper
Location: Basement		
Distribution Panel	System Grounding:	
Rating: 100 AMP	Description: Copper	
Description: Breakers	Location: Water Pipe	Ground Fault Circuit Interrupter:
Location: Basement		Location: Outside
Auxiliary Panel(s):	Outlets	Bathroom(s)
Rating: 100 AMP	Description: Grounded/Ungrounded	
Description: Breakers	Number of Outlets: Typical	Arc Fault Circuit Interrupter:
Location: Lane House		Location: Panel

Limitations

Main Disconnect Cover Not Removed

Observations/Recommendations

SERVICE ENTRANCE: **overall in good repair**
 Main Disconnect: **older, overall in good repair**
 SERVICE PANEL: **overall in good repair**
 Auxiliary Panel: **Lane House: newly installed**



BRANCH WIRING:
 Knob & Tube: **some noted in basement ceiling**
may require upgrading for insurance purposes

BRANCH WIRING: **newly installed in Lane House**

Note 1: All recommendations are safety issues - Treat them as high priority.

Note 2: Please ensure accurate labelling on panels.

Description

Description: Efficiency: Rated Input: Approx. Age: Life Expectancy: Fuel Type: Shut Off at:
 Forced Air Furnace: Mid 80 x1000BTU/hr 30 yrs. 20+ yrs. Gas Meter-Exterior

Exhaust Vent Arrangement:

Limitations

Furnace Performance

Heat Loss Calculations Not Done


Supply Temp F:
 Return Temp F:

Observations/Recommendations

FORCED AIR FURNACE: continue servicing until replacement becomes necessary
 recommend obtaining replacement parts/servicing contract
 consider upgrading to high efficiency unit

Filter: replace 1-per-3 months

Humidifier: old, replace



Ducts: older arrangement typical for age of house
 improve/upgrade if renovating

Lane House: new installations

Description			
Description:	Cooling Capacity:	Approx. Age:	Typical Life Expectancy:
Air Conditioner (air-cooled):	24 x1,000 BTU/hr	30 yrs. old	20 yrs.
Heat Pump (air-cooled)	15 12 x1,000 BTU/hr	x2 new yrs. old	

Limitations	Cooling Performance
	Supply Temp F:
	Return Temp F:

Observations/Recommendations

AIR CONDITIONER: not tested: should be serviced before using



DUCTLESS HEAT PUMP: Lane House
 newly installed
 unit provides cooling and supplemental heating
 refer to owners manual



Description

Material:	Location	R-Value	Air/Vapour Barrier:	Venting:
Fiberglass:	Main Roof:	40	Not Visible	Roof
Spray foam:	Lane House Roof	32		Heat Recovery Ventilator

Limitations

Access Not Gained To Wall Space
 Access Not Gained To Roof Space

Observations/Recommendations

ROOF SPACE: insulation (upgraded) and ventilation is adequate



Comments: Lane House: newly built: visible insulation in roof space

Heat Recover Ventilator: Lane House: provides house with better air quality and efficiency
 see owners manual for proper use and maintenance



Description

Service Piping into House:	Main Shut Off Valve at:	Water Flow (Pressure):	
Copper	Basement Utility Room : Lane House	Good	
Supply Piping & Pump(s):	Waste Piping & Pump(s):	Water Heater	
Copper	Plastic	Unit 1	Unit 2
Plastic	Cast Iron	Type: Conventional	Conventional
	Clay Floor Drain	Fuel Type: Gas	Electricity
		Capacity: 40 Gal	40 Gal
		Age Yrs.: 8	new
		Life Expectancy: 15	20

Limitations

Isolating/Relief Valves & Main Shut Off Valves Not Tested	Concealed Plumbing not Inspected
Kitchen and Laundry Appliances Were Not Inspected	Tub/Sink Overflows Not Tested

Observations/Recommendations

SUPPLY PIPING: [all piping examined was in good repair](#)

WASTE PIPING: [all piping examined was in good repair](#)

Basement Floor Drain: [older : recommend video-scan](#)

Floor Drain/Trap: [front yard older clean out suspect older main drain, recommend video-scan](#)
[recommend installing backflow valve to main waste drain](#)
[new plastic cleanout pipe\(s\) at rear basement appears to be for Lane House drainage](#)



Kitchen(s) [overall in good repair, older bath/faucet maintenance](#)
[Lane House new](#)

Washroom(s): [overall in good repair](#)
[Lane House new](#)

Description

Floor Finishes:	Wall Finishes:	Ceiling Finishes:	Windows:	Exterior Doors:
Wood	Plaster/Drywall	Plaster/Drywall	Sliders	Metal
Ceramic Tile			Fixed	Wood
			Skylight(s)	
Fireplaces:	Fireplace Fuel:			

Limitations

Restricted/No Access To: _____ Foundation Not Visible 60 %
 CO Detectors, Security Systems, Central Vacuum, Chimney Flues Not Inspected Drainage Tile Not Visible

Observations/Recommendations


Floors/Walls/Ceilings: overall in good repair
 Floors: some worn areas
 Ceilings: mud room: maintenance
 Floors/Walls/Ceilings: Lane House new

Trim/Cabinets/Counters: overall in good repair
 Trim/Cabinets/Counters: Lane House new

Windows/Doors: older units, upgrade as required or if renovating
 Windows/Doors: Lane House new

**Basement Leakage: presently no leaking detected with moisture meter random sampling
 typical efflorescence, staining and dampness for older foundation
 see steps below
 recommend damp-proofing if renovating basement

Comments: exterior east: ground between walls has been covered with plastic
 and gravel - likley to reduce risk of basement leaking - monitor



CO/Smoke detectors: please ensure one per level each with annual maintenance, this is a life safety concern and mandatory by law

** Steps recommended in order to minimize basement leakage

1. gutters, downspouts, grading, driveways: ongoing maintenance and repair/see Exterior
2. cracks/form ties on foundation: monitor/repair as required
3. excavation/damp-proofing: monitor basement, consider step 3 as a last resort

Environmental/Health Concerns: http://redbrickinspections.ca/docs/11_Environmental_Reference_Guide.pdf



Bob Papadopoulos P.Eng, RHI

- **Over 20 years of building inspecting experience in Toronto and the GTA**
- **Over 6,000 residential and commercial buildings inspected**

Bob has inspected over 6,000 residential and commercial buildings of various descriptions and reporting on conditions of major systems including structure, building envelope and mechanical systems, specific problem investigations and pre-renovation inspections. In the past Bob has helped train Home Inspectors and assisted in the creation of educational courses on home inspecting as well as taught Home Inspection courses at Seneca College. Bob also has experience in the construction industry inspecting many large scale projects through-out the GTA. He also served in the Canadian Navy as a Marine Mechanic and Ships Team Diver.

Professional Designations

- P.Eng. (Professional Engineer of Ontario) <http://www.peo.on.ca/>
 - RHI Registered Home Inspector <http://www.oahi.com/>
 - Environmental Site Assessment: ESA Phase 1 Certified <http://aesac.ca/>
-