

# HOME INSPECTION REPORT



9 Camborne Ave  
Toronto

Prepared for: Theodore Babiak Team

Prepared by: Bob Papadopoulos P.Eng., RHI \*

Inspection Date: April 8 2026



[www.redbrickinspections.ca](http://www.redbrickinspections.ca)  
[bob@redbrickinspections.ca](mailto:bob@redbrickinspections.ca)  
416-829-6655

Please Read: [http://redbrickinspections.ca/docs/1\\_Introduction\\_Reference\\_Guide.pdf](http://redbrickinspections.ca/docs/1_Introduction_Reference_Guide.pdf)

Please Read: <https://redbrickinspections.ca/home-inspection-terms-and-conditions/>

Please Read: <http://redbrickinspections.ca/wp-content/uploads/2015/06/StandardsofPractice-OAHI-Rev.pdf>

\* please see credentials at end of report

## SIGNIFICANT ITEMS

*This page should not be considered as the complete report.  
Please read all other forms contained within the Home  
Inspection Report*

*For the purposes of this report,  
the front of the house is considered  
to be facing: West*

ROOFING The roof surfaces through-out are overall in good repair.

EXTERIOR Overall well maintained. See details for general repairs and maintenance.

STRUCTURE Overall well built house.

ELECTRICAL The 100 AMP service size is adequate and the wiring is copper grounded and ungrounded -see details.

HEATING 15-yr-old high-efficiency forced-air gas furnace with a typical life expectancy of 20-yrs.

COOLING/  
HEAT PUMPS 10-yr-old air-conditioner with a typical life expectancy of 15-yrs.

INSULATION/  
VENTILATION Recommend additional insulation in the roof space to improve comfort and efficiency.

PLUMBING Overall good water pressure with copper supply piping. Further evaluation to main waste drain. The washrooms and kitchen are overall in good repair.

INTERIOR Main level overall well maintained. Anticipate basement floor repairs. There is evidence of past basement leaking - see details.

## OVERALL RATING

The following rating reflects both the original quality of construction and the *overall* current condition of the home, based on a comparison to *similar* homes.

Below Typical

Typical

Above Typical

*Prior to reviewing the Home Inspection Report please read the Terms and Conditions of the Home Inspection and the Standards of Practice of the Ontario Association of Home and Property Inspectors available online at:*

[www.redbrickinspections.ca](http://www.redbrickinspections.ca)

REFERENCE LINK [http://redbrickinspections.ca/docs/2\\_Roofing\\_Reference\\_Guide.pdf](http://redbrickinspections.ca/docs/2_Roofing_Reference_Guide.pdf)

9 Camborne Ave

# ROOFING/Chimneys

April 8 2026

page 2

## Description

Roofing Material: Asphalt Shingles:	Location: Slope:	Leakage Probability: Low	Chimney(s) Type: Brick:	Location: East
--	---------------------	-----------------------------	----------------------------	-------------------

## Limitations

Roof Inspected By: From Grade	Access Limited By: Height	Chimney Access Limited By:
----------------------------------	------------------------------	----------------------------

## Observations/Recommendations

Tree Branches: rear yard: retain arbourist for annual monitoring/trimming budget for partial/full tree removal

Sloped Surface: overall surface in good repair



Chimney(s): monitor/repair as required

Note: Recommend Annual Maintenance Contract for Roof Surface, Flashing Details and Chimney(s)

**Description**

Gutters & Downspouts: Aluminum:	Downspout(s) Discharge: Various Above Grade	Lot Topography: Towards House Away From House	Walls & Wall Structures: Brick Vinyl Siding
------------------------------------	--	---	---

**Limitations**

Exterior Inspection from Ground Level  
Storage in Garage

**Observations/Recommendations**

**\*\*Window wells: north side: might be required - see Interior Basement**  
**\*\*Walk(s)/Driveway(s): seal gaps along foundation wall**



**WALL SURFACES:**

Brick: overall in good repair, repair at front corner

**DOORS/WINDOWS: overall in good repair**

Vinyl Siding: trim repair at rear - minor



**ATTACHED GARAGE: older car door- budget to replace**



Note: Maintain Gutters & Downspouts annually. Extend Downspouts at least 6-feet away from the house

**\*\* Any or all these items may contribute to Basement Leakage. Please see Interior Page**

**Description**

Configuration: Basement:	Foundations: Poured Concrete	Floor : Wood Joists	Walls : Masonry (Double-Brick) Wood Frame (Siding)	Roof/Ceiling Framing: Wood Rafters/Joists
-----------------------------	---------------------------------	------------------------	--	--


**Limitations**

Restricted Access to: Wall Space	Foundation Wall Not Visible: <u>75</u> % Roof Space Inspected From Access Hatch
-------------------------------------	--

**Observations/Recommendations**

overall well built house



FOUNDATIONS: typical settlement crack under basement steps - prior repaired, see Interior Basement



Stair Opening: basement wood supports damaged at floor: reinforced with metal posts



ROOF: overall in good repair



**Description**


Service Size: <b>100</b> AMP (240volts)	Service Entrance Cable:	Distribution Wire:
Main Disconnect/Service Box	Location: <b>Overhead</b>	<b>Copper</b>
Rating: <b>100</b> AMP	Type of material: <b>Not Visible</b>	<b>Grounded &amp; Ungrounded</b>
Description: <b>Breakers</b>		
Location: <b>Basement</b>		
Distribution Panel	System Grounding:	
Rating: <b>100</b> AMP	Description: <b>Copper</b>	
Description: <b>Breakers</b>	Location: <b>Water Pipe</b>	Ground Fault Circuit Interrupter:
Location: <b>Basement</b>		Location:
Auxiliary Panel(s):	Outlets	
Rating: AMP	Description: <b>Grounded/Ungrounded</b>	
Description:	Number of Outlets: <b>Typical</b>	Arc Fault Circuit Interrupter:
Location:		Location:

**Limitations**

**Main Disconnect Cover Not Removed**

**Observations/Recommendations**

SERVICE ENTRANCE: **overall in good repair**  
 SERVICE PANEL: **overall in good repair**



Ungrounded Outlet(s): **provide GFCI's (ground fault circuit interrupters) and/or upgrade wiring if renovating**

Note 1: All recommendations are safety issues - Treat them as high priority.

Note 2: Please ensure accurate labelling on panels.

REFERENCE LINK [http://redbrickinspections.ca/docs/6\\_Heating\\_Reference\\_Guide.pdf](http://redbrickinspections.ca/docs/6_Heating_Reference_Guide.pdf)

9 Camborne Ave

# HEATING

April 8 2026

page 6

## Description

Description: Efficiency: Rated Input: Approx. Age: Life Expectancy: Fuel Type: Shut Off at:  
Forced Air Furnace: High 69 x1000BTU/hr 15 yrs. 20 yrs. Gas Meter-Exterior

Exhaust Vent Arrangement: Plastic Through-Wall Vent

## Limitations


Heat Loss Calculations Not Done  
Heat Exchanger- Inaccessible

## Furnace Performance

Supply Temp F: 110  
Return Temp F: 70

## Observations/Recommendations

FORCED AIR FURNACE: [service annually](#)  
[recommend obtaining replacement parts/servicing contract](#)  
Filter: [recommend properly sized for cabinet - refer to model#](#)



REFERENCE LINK

[http://redbrickinspections.ca/docs/7\\_AC\\_Heat\\_Pump\\_Reference\\_Guide.pdf](http://redbrickinspections.ca/docs/7_AC_Heat_Pump_Reference_Guide.pdf)

9 Camborne Ave

## COOLING/Heat Pumps

April 8 2026

page 7

### Description

Description:	Cooling Capacity:	Approx. Age:	Typical Life Expectancy:
Air Conditioner (air-cooled):	24 x1,000 BTU/hr	10 yrs. old	10 to 15 yrs.

### Limitations

Cannot Test With Low Outdoor Temp  
Outdoor Coil Covered

### Cooling Performance

Supply Temp F:  
Return Temp F:

### Observations/Recommendations

AIR CONDITIONER: not tested: should be serviced before using



**Description**

Material:	Location	R-Value	Air/Vapour Barrier:	Venting:
Fiberglass:	Main Roof:	24	Kraft Paper	Roof Gable

**Limitations**

Roof Space Inspected from Access Hatch

Access Not Gained To Wall Space

**Observations/Recommendations**

ROOF SPACE: recommend upgrading insulation to improve comfort and efficiency  
uneven distribution of insulation - improve/add insulation



**Description**

Service Piping into House: Copper	Main Shut Off Valve at: Basement	Water Flow (Pressure): Below Average
Supply Piping & Pump(s): Copper	Waste Piping & Pump(s): Plastic Cast Iron Clay Floor Drain	Water Heater Type: Conventional Fuel Type: Gas Capacity: 40 Gal Age Yrs.: 5 Life Expectancy: 15

**Limitations**

Isolating/Relief Valves & Main Shut Off Valves Not Tested	Concealed Plumbing not Inspected
Kitchen and Laundry Appliances Were Not Inspected	Tub/Sink Overflows Not Tested

**Observations/Recommendations**

SUPPLY PIPING: all piping examined was in good repair

WASTE PIPING: all piping examined was in good repair  
 suspect older main drain, recommend video-scan, risk of tree roots  
 recommend installing backflow valve to main waste drain  
 new plastic cleanout pipe(s) at front basement suggests some drain upgrades

Washroom(s): overall in good repair

Kitchen(s) overall in good repair



**Description**

Floor Finishes:	Wall Finishes:	Ceiling Finishes:	Windows:	Exterior Doors:
Wood	Plaster/Drywall	Plaster/Drywall	Sliders	Metal
Ceramic Tile	Paneling		Fixed	
Fireplaces:		Fireplace Fuel:		

**Limitations**

Restricted/No Access To:	Foundation Not Visible <u>75</u> %
CO Detectors, Security Systems, Central Vacuum, Chimney Flues Not Inspected	Drainage Tile Not Visible

**Observations/Recommendations**

Windows/Doors: overall in good repair  
 Trim/Cabinets/Counters: overall in good repair  
 Floors/Walls/Ceilings: main level: overall in good repair

Floors/Walls/Ceilings: basement: anticipate renovations  
 Floors: basement: damaged, possibly water damage due to prior basement and/or plumbing leaks and/or furnace leak  
 Floors: basement: damaged, possibly due to moisture from concrete floor  
 \*\*Basement Leakage: presently no leaking detected with moisture meter random sampling typical efflorescence, staining and dampness for older foundation suspect prior leaking at rear of basement, prior foundation repair under steps, monitor, might require/recommend damp-proofing if renovating basement see steps below



CO/Smoke detectors: please ensure one per level each with annual maintenance, this is a life safety concern and mandatory by law

\*\* Steps recommended in order to minimize basement leakage

1. gutters, downspouts, grading, driveways: ongoing maintenance and repair/see Exterior
2. cracks/form ties on foundation: monitor/repair as required
3. excavation/damp-proofing: monitor basement, consider step 3 as a last resort

Environmental/Health Concerns: [http://redbrickinspections.ca/docs/11\\_Environmental\\_Reference\\_Guide.pdf](http://redbrickinspections.ca/docs/11_Environmental_Reference_Guide.pdf)



## **Bob Papadopoulos P.Eng, RHI**

---

- **Over 20 years of building inspecting experience in Toronto and the GTA**
- **Over 6,000 residential and commercial buildings inspected**

Bob has inspected over 6,000 residential and commercial buildings of various descriptions and reporting on conditions of major systems including structure, building envelope and mechanical systems, specific problem investigations and pre-renovation inspections. In the past Bob has helped train Home Inspectors and assisted in the creation of educational courses on home inspecting as well as taught Home Inspection courses at Seneca College. Bob also has experience in the construction industry inspecting many large scale projects through-out the GTA. He also served in the Canadian Navy as a Marine Mechanic and Ships Team Diver.

### **Professional Designations**

- P.Eng. (Professional Engineer of Ontario) <http://www.peo.on.ca/>
  - RHI Registered Home Inspector <http://www.oahi.com/>
  - Environmental Site Assessment: ESA Phase 1 Certified <http://aesac.ca/>
-