

July 18/25

To Whom it May Concern

RE: 82 Humberview Road, Toronto

Solda Pools Installed the pool in 2005.

Solda Service has opened & closed the pool each year since installation.

The pool is in good working order.

Solda Service replaced the liner in July 2025.

If you have any questions, please do not hesitate to contact our office.

Sincerely,



William Burns

Service Manager